

HHSEGS (11-AFC-02)
TESTIMONY OF C.R. MACDONALD

TRAFFIC & TRANSPORTATION
EXHIBIT 719

PHOTO GALLERY

Traffic & Transportation: Photo 1

SR160 westbound overlooking the proposed HHSEGS project site near the dry lake. 1/02/13.



Traffic & Transportation: Photo 2

Junction of SR160 and Old Spanish Trail Highway/Tecopa Road looking north towards Pahrump.



Traffic & Transportation: Photo 3

A mobile retailer often offers jerky products at the SR160/Old Spanish Trail Hwy/Tecopa Rd. junction while ammo suppliers seek to capitalize on gun enthusiasts. 5/17/12



Traffic & Transportation: Photo 4

Looking east at the SR160 and Old Spanish Trail Highway/Tecopa Road junction though ammunition advertising has recently been removed. Note condition of roadway edge. 1/02/13



Traffic & Transportation: Photo 6

Potholes and crumbling curbs located on the “Nevada” side of Old Spanish Trail Hwy/Tecopa Rd. looking southwest about 3-4 miles from the proposed project site. 5/17/12



Traffic & Transportation: Photo 7

Potholes and crumbling curbs located on the “Nevada” side of Old Spanish Trail Hwy/Tecopa Rd. looking southwest about 3-4 miles from the proposed project site. 5/17/12



Traffic & Transportation: Photo 8

View of Old Spanish Trail Hwy/Tecopa Rd.'s and the road condition looking west slightly west of St. Therese Mission. 5/17/12



Traffic & Transportation: Photo 10

Temporary road repairs are evident along the Old Spanish Trail Hwy/Tecopa Rd. slightly west of St. Therese Mission (in background) and looking northeast. This is the only kind of maintenance this road has received since it was established (1960's?). 5/17/12



Traffic & Transportation: Photo 11

Westbound on Old Spanish Trail Hwy/Tecopa Rd.
slightly west of the proposed HHSEGS Common Area entrance. 5/17/12



Traffic & Transportation: Photo 12

Charleston View residence 300 ft. east of the proposed HHSEGS property line looking north down
Crystal Rd (as shown in Traffic & Trans: Photo 11) along the proposed fence line of Solar II. 1/02/13



Traffic & Transportation: Photo 13

View of Charleston View residence 300 ft. east of the HHSEGS boundary in background and adjacent to Solar II's heliostat field. Monitoring Well #3 test area in foreground. 1/02/13



Traffic & Transportation: Photo 14

View of Charleston View dumpsters adjacent to the Old Spanish Trail Highway/Tecopa Road looking east. St. Therese is in the background and the proposed HHSEGS will be sited on the left. 1/02/13.



Traffic & Transportation: Photo 15

Looking north directly into the proposed HHSEGS solar field and Solar 2's power tower. 1/02/13



Traffic & Transportation: Photo 16

View of residence known as CR1 in background, 950 ft. south of the HHSEGS boundary.
Old Spanish Trail Highway/Tecopa Road is in foreground, dumpsters and
community bulletin board in the middle. 1/02/13



Traffic & Transportation: Photo 17

View of of Charleston View residence known as CR1 from Orchard Well.
Old Spanish Trail Hwy/Tecopa Rd. in middle. 12/20/11.



Traffic & Transportation: Photo 18

Looking east at the residence known as CR1.
The community mailboxes are in the foreground. 1/02/13.



Traffic & Transportation: Photo 19

Looking west from Carpenter Ave., which is slightly east of the residence known as CR1 and one of the two main entrances into Charleston View "proper". The dumpsters are in the background and the proposed project will be directly adjacent to the Old Spanish Trail Highway/Tecopa Road on the right. 1/02/13.



Traffic & Transportation: Photo 20

View of Carpenter Avenue looking northwest into the proposed HHSEGS project site. 1/02/13.



Traffic & Transportation: Photo 21

Charleston View looking east at Mt. Potosi on the Old Spanish Trail Highway/Tecopa Road. Rose Avenue, one of the two main entrances into Charleston View “proper”, is in the middle and St. Therese is visible in the background. 1/02/13.



Visual Resources: Photo 22

Looking east along Old Spanish Trail Highway/Tecopa Road at Rose Avenue, which sits directly across the Firewater Tank and the Orchard Well area. St. Therese can be seen in the distance. 1/02/13.



Traffic & Transportation: Photo 23

View of Rose Avenue looking south a few hundred feet from Orchard Well. Rose Avenue is the road KOP4 was taken from approximately 0.5 miles south from this location. 1/02/13.




Traffic & Transportation: Photo 24

View from Rose Avenue looking north at HHSEGS project site. Yellow cap of monitoring test well is visible in the background. Orchard Well is located about 300 ft. to the left. 1/02/13.



Traffic & Transportation: Figure 1
Proposed HHSEGS project site and Charleston View.



Traffic & Transportation: Photo 25

Flood waters wash soil over Old Spanish Trail Hwy/Tecopa Rd after 10/11/12 flood event. Location is shortly before reaching the CA/NV Stateline and approximately 0.5 miles from St. Therese. 10/15/12



Traffic & Transportation: Photo 26

Flood waters wash soil over Old Spanish Trail Hwy/Tecopa Rd after 10/11/12 flood event. Location is slightly west of St. Therese. 10/12/12



Traffic & Transportation: Photo 27

Passing vehicle kicks up dust from soil erosion on Old Spanish Trail Hwy/Tecopa Rd. left over from 10/11/12 flood event slightly east of Charleston View and adjacent to the proposed HHSEGS site.



Traffic & Transportation: Photo 28

“Road Subject To Flooding” sign posted adjacent to the proposed HHSEGS site west of St. Therese and east of Charleston View “proper”. 5/14/12



Traffic & Transportation: Photo 29

Flooding across Old Spanish Trail Hwy/Tecopa Rd. on 7/23/12 flood event looking north into the proposed HHSEGS project sites western boundary area.
Photo courtesy of Basin & Range Watch.



Traffic & Transportation: Photo 30

Eastbound on Old Spanish Trail Hwy/Tecopa Rd. coming from Tecopa and overlooking Charleston View. About 15 miles west (in opposite direction) is Emigrant Pass. 1/02/13



Traffic & Transportation: Photo 31

Road sign warning motorists of upcoming “serious curves” through Emigrant Pass. 1/02/13



Traffic & Transportation: Photo 32

One of the most serious curves on Emigrant Pass. Visibility of oncoming traffic is zero. 1/02/13



Traffic & Transportation: Photo 33
More “serious curves” on Emigrant Pass. 1/02/13



Traffic & Transportation: Photo 35
Spray painted warning to motorists about Emigrant Pass dangers. 1/02/13



Traffic & Transportation: Photo 36

Another warning to motorists about Emigrant Pass dangers. 1/02/13



Traffic & Transportation: Photo 37

Narrow roadways and zero visibility leave little place to go. 1/02/13

